



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On: LCB2000/250

Compiled By: C.WEDGE

Date Compiled: 19/01/00

Number	6172-459
Issue	5
Date	26/07/01
CN Number	21126

Apply voltages.

This is the default state at the beginning of each test:

LINE, NEUTRAL, EARTH and RECTIFIER OUT are high voltage inputs. If not in use they need to be disconnected from the UUT.

First Group interboard connectors: top left

PL500	-5V LPP	S	-5V	PL501	+5V LPP	S	+5V
PL502	20V	S	20V	PL503	N-E IN	AO	
PL504	25A ON	DI	(0V)	PL505	TB-E IN	AO	
PL506	25A CUTOUT	AO		PL507	L-Ex10	AO	
PL508	-5V	S	-5V	PL509	N-Ex10	AO	
PL511	L-N IN	AO		PL512	L-E IN	AO	

Second group - by range switch.

PL515	+5V	S	+5V	PL516	50HZ CLK	AO	
PL517	MAINS LANE	AO		PL518	ZERO CROSS	AO	
PL519	NOT USED			PL520	ZERO I MON	AO	
PL521	0V	S	0V	PL522	RL NorL	RI	(+5V)
PL523	RCD DRIVE	AI	(0V)	PL524	RELAY POWER	S	+5V
PL525	MID RANGE	DI	(0V)	PL526	RL N	RI	(+5V)
PL527	NOT USED			PL528	RL NorE	RI	(+5V)
PL529	NOT USED			PL530	NOT USED		
PL531	NOT USED			PL532	TEMPCD	AO	
PL533	STROBE	DI	(+5V)	PL534	HI RANGE	DI	(0V)

Key:

S Supply
 DI Digital input
 DO Digital output
 AI Analogue input
 AO Analogue output
 RI Relay input ~ 50mA drive for each relay.

Check PCB power consumption

- 1) Check power consumption of +5V rail = < 15mA
- 2) Check power consumption of -5V rail = < 15mA
- 3) Check power consumption of +20V rail = < 10mA

Check supply measurement op-amps (Sheet 1)**L-N Voltage**

- 4) Connect LINE = 0V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin7 = -100mV to 100mV
- 5) Connect LINE = +300V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin7 = 1.2V to 1.6V
- 6) Connect LINE = -300V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin7 = -1.6V to -1.2V



AF008-01-0997

TEST SPECIFICATION PCB (LCB)1st Used On:

LCB2000/250

Compiled By:

C.WEDGE

Date Compiled:

19/01/00

Number
Issue
Date
CN Number**6172-459**
5
26/07/01
21126**L-E & LEx10 Voltage**

- 7) Connect LINE = 0 V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin1 = -100mV to 100mV
- 8) Check PL507 = -100mV to 100
- 9) Connect LINE = +30V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin1 = 120mV to 160mV
- 10) Check PL507 = -1.6V to -1.2V
- 11) Connect LINE = +300V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin1 = 1.2V to 1.6V
- 12) Connect LINE = -30V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin1 = -160mV to -120mV
- 13) Check PL507 = 1.2V to 1.6V
- 14) Connect LINE = -300V , NEUTRAL = 0V , EARTH = 0V Check IC502 pin1 = -1.6V to -1.2V

N-E & NEx10 Voltage

- 15) Connect LINE = 0V , NEUTRAL = 0V , EARTH = 0V Check IC507 pin7 = -100mV to 100mV
- 16) Check PL509 = -100mV to 100
- 17) Connect LINE = 0V , NEUTRAL = +30V , EARTH = 0V Check IC502 pin1 = 120mV to 160mV
- 18) Check PL507 = -1.6V to -1.2V
- 19) Connect LINE = 0V , NEUTRAL = +300V , EARTH = 0V Check IC502 pin1 = 1.2V to 1.6V
- 20) Connect LINE = 0V , NEUTRAL = -30V , EARTH = 0V Check IC502 pin1 = -160mV to -120mV
- 21) Check PL507 = 1.2V to 1.6V
- 22) Connect LINE = 0V , NEUTRAL = -300V , EARTH = 0V Check IC502 pin1 = -1.6V to -1.2V

Touch button and adjust pot

- 23) Connect LINE = 0V , NEUTRAL = 0V , EARTH = 0V , TOUCH BUTTON = 0V
Check PL505 = -100mV to 100mV
- 24) Connect LINE = +300V , NEUTRAL = +300V , EARTH = 0V , TOUCH BUTTON = 0V
Check PL509 = -10mV to 10mV Adjust R513 if necessary
- 25) Connect LINE = 0V , NEUTRAL = +30V , EARTH = 0V , TOUCH BUTTON = +200V
Check PL505 = -2.4V to -0.8V

Switch relays on and check 50Hz CLK, Mains lane, ZERO I MON and ZERO CROSS. (Sheet 1 & 3)

Switch relays to L-N: RL N = ON , RL NorL = ON , RL Nor E = OFF

- 26) Connect LINE = 0V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = -500mV to 500mV
- 27) Check Mains Lane = -500mV to 500mV
- 28) Check ZERO I MON = -500mV to 500mV
- 29) Check ZERO CROSS = 4V to 6V
- 30) Connect LINE = +300V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = -1.6V to -1.2V
- 31) Check Mains Lane = 1.7V to 2.1V
- 32) Check ZERO I MON = 4V to 6V
- 33) Check ZERO CROSS = 4V to 6V
- 34) Connect LINE = -300V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = 1.2V to 1.6V
- 35) Check Mains Lane = 1.7V to 2.1V
- 36) Check ZERO I MON = 4V to 6V
- 37) Check ZERO CROSS = -500mV to 500mV

Switch relays to L-E: RL N = OFF , RL NorL = ON , RL Nor E = ON



AF008-01-0997

TEST SPECIFICATION PCB (LCB)1st Used On:

LCB2000/250

Compiled By:

C.WEDGE

Date Compiled:

19/01/00

Number
Issue
Date
CN Number**6172-459**
5
26/07/01
21126

- 38) Connect LINE = 0V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = -500mV to 500mV
39) Check Mains Lane = -500mV to 500mV
40) Check ZERO I MON = -500mV to 500mV
41) Check ZERO CROSS = 4V to 6V
42) Connect LINE = +300V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = -1.6V to -1.2V
43) Check Mains Lane = 1.7V to 2.1V
44) Check ZERO I MON = 4V to 6V
45) Check ZERO CROSS = 4V to 6V
46) Connect LINE = -300V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = 1.2V to 1.6V
47) Check Mains Lane = 1.7V to 2.1V
48) Check ZERO I MON = 4V to 6V
49) Check ZERO CROSS = -500mV to 500mV

Switch relays to N-E: RL N = ON , RL NorL = OFF , RL Nor E = ON

- 50) Connect LINE = 0V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = -500mV to 500mV
51) Check Mains Lane = -500mV to 500mV
52) Check ZERO I MON = -500mV to 500mV
53) Check ZERO CROSS = 4V to 6V
54) Connect LINE = +300V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = -1.6V to -1.2V
55) Check Mains Lane = 1.7V to 2.1V
56) Check ZERO I MON = 4V to 6V
57) Check ZERO CROSS = 4V to 6V
58) Connect LINE = -300V , NEUTRAL = 0V , EARTH = 0V Check 50HZ CLK = 1.2V to 1.6V
59) Check Mains Lane = 1.7V to 2.1V
60) Check ZERO I MON = 4V to 6V
61) Check ZERO CROSS = -500mV to 500mV

Check dynamic load circuit (Sheet 3)

Connect +48V to RECTIFIER OUT
Set RCD Drive to 2V

- 62) Check current from 48V = -500uA to 500uA
63) Set strobe = low Check current from 48V = 18mA to 22mA
64) Check voltage across R584 = 1.6V to 2.2V
65) Set mid current = high Check current from 50V = 180mA to 220mA
66) Check voltage across R584 = -100mV to 100mV

Check 25A ON & cutout circuit (Sheet 3)

- 67) Check 25A cutout = 4.5V to 5.5V
68) Take 25A ON = high Check 25A cutout = 1.0V to 3V

Check temperature measurement

- 69) Check TEMPCD = 600mV to 1000mV



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On:

LCB2000/250

Compiled By:

C.WEDGE

Date Compiled:

19/01/00

Number

6172-459

Issue

5

Date

26/07/01

CN Number

21126

General – All tests

For the majority of tests the processor is held in reset state and PLD outputs are disabled by pulling OE- on TP397 high.

This assumes that the display and backlight is fitted, but not the rotary switch.

Power Supply – Main Board Sheet 2

'BATTERY TEST' low for all these tests. Connect 500 ohm resistor 'RELAY POWER' to 0V.

		Rotary Switch	PRETEST PWR-	20V ON	GEN POWER OFF	RELAY PS	Tests
		TP90	TP108	TP112	TP67	TP71	
1_1	Switched off	High	X	X	X	X	Current < 100µA
2_1	Standby	Low	High	Low	High	High	Current < 600µA
3_1							Vcc = 5V ± 0.1V
4_1	Switched on	Low	Low	Low	Low	Low	Current < 100mA
4_2							+5VLPP = 5V ± 0.1V
4_3							+5V = 5V ± 0.1V
4_4							-5VLPP = -5V ± 0.3 V
4_5							-5V = -5V ± 0.3V
4_6							'RELAY POWER' = 5V ± 0.1V
5_1	Power Save Relays	Low	Low	Low	Low	High	'RELAY POWER' = 3.8V ± 0.5V
6_1	Switch 20V on	Low	Low	High	Low	Low	'20V' = 22V ± 2V

Check battery test circuit.

7_1 Check BROWNOUT REF (TP66) = 0.6V ± 0.1 V

8_1 BATTERY TEST = Low, Check BATT/2 = 0

8_2 BATTERY TEST = High, Check BATT/2 = 4.5V ± 0.1 V (Assuming driven off 9V).



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On: LCB2000/250

Compiled By: C.WEDGE

Date Compiled: 19/01/00

Number
Issue
Date
CN Number**6172-459**
5
26/07/01
21126

Mux, PSD and AMP – Main Board Sheet 1(A)

	Analogue Inputs					Digital Inputs					Output
	L-EX10	N-EX10	L-E IN	N-E IN	L-N IN	INA	INB	INC	ZERO CROSS	INV ZERO CROSS	Check TP6
9_1	0V	0V	0V	0V	0V	0	0	0	0	1	0V±0.1V
10_1	0.6V	0V	0V	0V	0V	0	0	0	0	1	3V ± 0.3V
11_1	-0.6V	0V	0V	0V	0V	0	0	0	0	1	-3V ± 0.3V
12_1	0V	0.6V	0V	0V	0V	1	0	0	0	1	3V ± 0.3V
13_1	0V	0V	0.6V	0V	0V	0	0	1	0	1	-3V ± 0.3V
14_1	0V	0V	0V	0.6V	0V	1	0	1	0	1	-3V ± 0.3V
15_1	0V	0V	0V	0V	0.6V	0	1	1	0	1	-3V ± 0.3V
16_1	0V	0V	0V	0V	0.6V	0	1	1	0	0	3V ± 0.3V
17_1	0V	0V	0V	0V	0.6V	0	1	1	1	0	-3V ± 0.3V

Difference measurement – Main Board Sheet 1(B)

We need to drive the output of IC 4 (TP6 above) with 3V). The easiest way to do this is to set from above

L-EX10	N-EX10	L-E IN	N-E IN	L-N IN	INA	INB	INC	ZERO CROSS	INV ZERO CROSS
0.6V	0V	0V	0V	0V	0	0	0	0	1

Check we are working:

	CAP/ZERO	UNLOADED	LOADED	VD TP18
18_1	1 for 200ms	0	0	0V ± 0.1V
18_2	0	1 for 200ms	0	1.5V ± 0.1V
	0	0	1 for 200ms	

18_3 Repeat the above sequence, measuring and displaying the final '0V' output. Adjust R6 for minimum.

18_4 Repeat the above sequence, measuring the intermediate '1.5V' output. Adjust R5 for 1.66V+/-0.02V



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On: LCB2000/250

Compiled By: C.WEDGE

Date Compiled: 19/01/00

CN Number

Number
Issue
Date

6172-459
5
26/07/01
21126

Mux and AC-DC convertor – Main Board Sheet 4

	Analogue inputs			Driven by IC2 via 10k's		Digital inputs				Outputs	
	L-N IN	L-E IN	N-E IN	N-E	L-E	AC/DCin A	AC/DCin B	ZERO I MON	ZERO CROSS	AC/Dc out	L- E/FREQ
19_1 19_2	0	0	0	0	0	0	0	0	0	0V ±0.1V	0
20_1 20_2	0	0	0	0	0	0	1	0	0	0V ±0.1V	0
21_1 21_2	0	0	0	0	0	1	0	0	0	0V ±0.1V	0
22_1 22_2	0	0	0	0	0	1	1	0	0	0V ±0.1V	0

	Analogue inputs			Driven by IC2 via 10k's		Digital inputs				Outputs	
23_1 23_2	3V	0	0	0	0	0	0	0	1	2.4V ± 0.3V	1
24_1 24_2	-3V	0	0	0	0	0	0	0	1	2.4V ± 0.3V	1
25_1 25_2	0	3V	0	0	1	1	0	0	0	2.4V ± 0.3V	1
26_1 26_2	0	0	3V	1	0	0	1	0	0	2.4V ± 0.3V	1
27_1	0	0	0	0	0	1	1	1	0	X	1

Mux and Referances – Main Board Sheet 3(A)

	TP87	TP88	ADCinA	ADCin B	AD REF HI	AD IN HI
28_1 28_2	0	0	1	0	0.987 V ± 2%	0V ± 0.1V
29_1 29_2	0	3V	0	0	X	3V ± 0.3V
30_1 30_2	1V	1V	0	0	254 mV ± 2%	1V ± 0.1V
31_1 31_2	1V	-3V	0	1	26 mV ± 2%	-3V ± 0.3V



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On:

LCB2000/250

Compiled By:

C.WEDGE

Date Compiled:

19/01/00

Number

6172-459

Issue

5

Date

26/07/01

CN Number

21126

Frequency window comparators – Main Board Sheet 5(A)

	L-E IN	L-E (TP9)
32_1	0V	+5V
32_2	1V	0V
32_3	-1V	0V

	N-E IN	N-E (TP10)
33_1	0V	+5V
33_2	1V	0V
33_3	-1V	0V

Buzzer – Main Board Sheet 5(C)

34_1 Apply 2kHz square wave to BUZZ (TP302). Check buzzer sounds.

EEPROM – Display Board Sheet 6(A)

35_1 Test as per CM500

Mux – Display Board Sheet 6(B)

	TEMP AB	TEMPCB	TP303	TP304
36_1	2V	1V	0	2V
36_2	2V	1V	1	1V

Backlight – Display Board Sheet 7(A)

37_1 'BACKLIGHT ON' low, check backlight is off
37_2 'BACKLIGHT ON' high, check backlight is on.

Watchdog, Reset Brownout and NMI – Display Board Sheet 9, and Brownout – Main Board Sheet 3

38_1 Switch off all supplies and drive VCC to 0V. Drive VCC to 5V and check for 40 - 110mS pulse on TP382.

Restore all supplies to normal.

38_2 Pulse WATCHDOG. Check for 65 - 220mS pulse on IC304 pin 12 (TP487).

Take TP70 High

39_1 Check for high on BROWNOUT-
Take TP70 low

39_2 Check for low on BROWNOUT-.



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On: LCB2000/250

Compiled By: C.WEDGE

Date Compiled: 19/01/00

Number

6172-459

Issue

5

Date

26/07/01

CN Number

21126

Relay Drivers – Main board sheet 3

	Drive Digital	Digital Inputs			Pull high with 1k resistors		
	RL TEST DISABLE TP413	RLY(0)	RLY(1)	RLY(2)	RL NorE	RL N	RL NorL
40_1	0	1	1	1	1	1	1
40_2	0	0	1	1	1	1	0
40_3	0	1	0	1	1	0	1
40_4	0	1	1	0	0	1	1
40_6	1	0	1	1	1	1	1
40_6	1	1	0	1	1	1	1
40_7	1	1	1	0	1	1	1

PLD Clock – Display Board Sheet 10

Input : 50Hz CLK. Outputs CLOCK1 and CLOCK2.

41_1 Take 50Hz CLK -5V -> +5V and check for pulse on CLOCK2 (300 -1100µS)**41_2** Take 50Hz CLK +5V -> -5V and check for pulse on CLOCK1. (300 -1100µS)**'Load on' monostable – Display Board Sheet 10****42_1** Take LOAD ON low-high and check for 5 – 30mS pulse on TP432**25A multivibrator – Display Board Sheet 11****43_1** With STROBE 25A low, check for 0 Hz on 25A ON.**43_2** Take STROBE 25A high and check for square wave.**PLD – Display Board Sheet 11**

This does not test the PLD functionally, just a check that it's present and has (probably) the correct program. This is done by writing to the ports and checking the outputs.

Write to a port by selecting it with A0 and clocking it in with CE (pulse high). The ports are 'write – through' when CE is high.

44_1 PORT 0 = \$55 and check for the following

0	Spare Output	1
1	ADCinA	0
2	ADCinB	1
3	AC/DCinA	0
4	AC/DCinA	1
5	(MODE 0)	NA
6	(TRIGGER)	NA
7	IN A	0



AF008-01-0997

TEST SPECIFICATION PCB (LCB)

1st Used On:

LCB2000/250

Compiled By:

C.WEDGE

Date Compiled:

19/01/00

Number
Issue
Date
CN Number**6172-459**
5
26/07/01
21126

44_2 PORT 0 = \$AA and check for the following

0	Spare Output	0
1	ADCinA	1
2	ADCinB	0
3	AC/DcinA	1
4	AC/DCinA	0
5	(MODE 0)	NA
6	(TRIGGER)	NA
7	IN A	1

45_1 PORT 1 = \$55 and check for the following

0	(LOAD SEL A)	NA
1	(LOAD SEL B)	NA
2	SPARE	1
3	20V ON	0
4	RELAY PS	1
5	LOAD ON	0
6	(HI I LOOP)	NA
7	(MODE 1)	NA

45_2 PORT 1 = \$AA and check for the following

0	(LOAD SEL A)	NA
1	(LOAD SEL B)	NA
2	SPARE	0
3	20V ON	1
4	RELAY PS	0
5	LOAD ON	1
6	(HI I LOOP)	NA
7	(MODE 1)	NA

RCD Circuit Current Control

As with the CM400 and CM500 IC313 is dual DAC. You write to this using DAC/AD, DAC/WR- and the data bus.

46_1 Apply 3V to MAINS LANE, and write \$80 to DAC A. Adjust R391/R389 for $-1.5V \pm 15 \text{ mV}$ on TP456 (output of IC311)

46_2 Write \$FF to DAC A and \$80 to DAC B. Adjust R393/R388 for $1.5V \pm 15 \text{ mV}$ on TP448 (output of IC311)

46_3 With 20V supply on and RCD OPT1 = 0 , check RCD DRIVE is 6V.

46_4 Take RCD OPT1 high and check RCD DRIVE is 12V.

46_5 Take MAINS LANE to 0V and Adjust for minimum output on R383.



AF008-01-0997

TEST SPECIFICATION PCB (LCB)1st Used On: LCB2000/250 Compiled By: C.WEDGE Date Compiled: 19/01/00

Number	6172-459
Issue	5
Date	26/07/01
CN Number	21126

Start up processor and check display and operation

This test starts the board up, fooling it that there's a Power Board attached connected to a 240V 50Hz L-PE. We can therefore check that the processor and A/D runs ok in pre-test mode. Running a test is complex and therefore not attempted.

This is the sequence:

Apply 9V battery voltage, (instrument switched off - i.e. TP90 0V)

Connect TEMPCD to 0.7 V

L-E to 3V pk-pk 50Hz

L-E/FREQ to 5V

TP122 to battery +ve

TP120 to 'Switch A' and 0V to 'Switch B' (Loop L-PE Switch position)

47_1 The board should power up into 'CAL' mode – there will be display test, followed by version number, checksum, 'CAL' and the L-PE voltage (should be 180V to 220V).

Note that error and faults are possible at this stage, as self-checking is carried out as the board powers up. Refer to separate lists for details.

LCB2500 ONLY from here – RS232 circuits

RS232 Transceiver - main board sheet 5

48_1 Check reading received from RS232 is 180 to 220V

Isolated transceiver – sheet 12

49_1 Connect –10V to PL700 pin 2. Check D705 unlit

50_1 Connect +10V to PL700 pin 2. Check D705 is lit

51_1 Check PL700 pin 3 –6V to –13 V

52_1 Shine a light onto D705. Check PL700 pin 3 +6 to +13V