

pH Calibration Checker

Troubleshooter tells you if your pH meter is in calibration

Features:

- Simulates values for pH 4, 7 and 10 ($\pm 0.1\%$ FS accuracy)
- Simple to use - connect the calibration cable to device needing calibration and select simulation range
- High Ohm range for industrial applications
- Easy verification - if your pH meter displays the same value that is being simulated, then it is in calibration
- Dims/Wt: 3.5x2.3x1" (60x92x25mm)/10oz (284g)
- Complete with 9V battery; CE approved, one year warranty



Ordering Information:

610022-BpH Calibration Checker with BNC cable